

Example – Electrical appliance with fire risk

Alert number: A12/01465/21

Published on 28/10/2021 in web report Report-2021-43

[Print](#)

Risk type	Fire
Notifying country	Croatia
Alert number	A12/01465/21



[View all](#)

1 Media files

Due to inadequate thermal protection, the windings of the motor could overheat leading to a fire.
The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335.

Category	Electrical appliances and equipment
Product	Mixer with bowl