Example – Electrical appliance with electric shock risk

Alert number: A12/01271/21

Published on 02/09/2021 in web report Report-2021-35

Print

Risk type Electric shock

Notifying country

Italy

Alert number

A12/01271/21



View all

3 Media files

The live pin holes of the sockets are not automatically shuttered when a plug is not inserted. As a result, water could enter and a user or a child could insert an object into live parts and receive an electric shock.

The product does not comply with the requirements of the Low Voltage Directive and the relevant national standard.

Category Electrical appliances and equipment

Product Extension lead