Alert number: A12/01242/22

Published on 01/09/2022 in web report Report-2022-35

Print



The rope of the swing has no pre-fixed hangers. As a result, the swing can be assembled improperly and the knots may easily get loose. A child may fall down and suffer injuries. The product has accessible openings and accessible holes, in which children can become trapped or suffer injuries. The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-8.

Category	Toys
Product	Plastic swing