

Example – Toy with strangulation risk

Alert number: A12/0366/18

Published on 08/03/2018 in web report Report-2018-010

Print

Risk type	Choking Strangulation
Notifying country	United Kingdom
Alert number	A12/0366/18



[View all](#)

3 Media files

The ribbon around the neck of the toy detaches easily, allowing access to the small bell. The bell which detaches may be put in the mouth by a child, causing choking and the ribbon collar could be put over a child's head, causing a strangulation hazard. The product does not comply with the requirements of the Toys Safety Directive and the relevant European Standard EN 71.

Category	Toys
Product	Soft Toy Cat